

Options polyamide and aluminium sensor boxes

- Membrane vent



Membrane vent

Image: Membrane vent for avoidance of condensation water

- Harting connection



Image: Harting connection = rapid changing the sensor box

- 2D indicator




Image: 2D plastic indicator yellow in the cover under the window